

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, IL 60604-3590

## OCT 3 0 2017

REPLY TO THE ATTENTION OF:

## CERTIFIED MAIL 7017 0660 0000 3661 8861 RETURN RECEIPT REQUESTED

WC-15J

Tag Lane Dairy Farm
Ex. 6. (Personal Privacy)
Ex. 6. (Personal Privacy)
Ixonia, Wisconsin 53036

Subject: Tag Lane Dairy Farm, April 27, 2017 U.S. EPA Clean Water Act Inspection Report; WI-0063932-01-0



On April 27, 2017, U.S. Environmental Protection Agency followed up on a complaint that Tag Lane Dairy Farm may be discharging through their Vegetated Treatment Area. The purpose of the EPA inspection was to determine if Tag Lane Dairy Farm was discharging process wastewater from its production area through its VTA into the culvert under River Valley Road into the unnamed tributary that flows to Rock Creek. Enclosed is a copy of EPA's inspection report.

Tag Lane Dairy Farm is a large Concentrated Animal Feeding Operation (CAFO) as defined in 40 C.F.R. § 122.23.

If you have any questions or concerns regarding this letter, or the inspection report, please contact Cheryl Burdett at (312) 886-1463 or <u>burdett.cheryl@epa.gov</u>

Sincerely,

Ryan Bahr Chief, Section II

Water Enforcement and Compliance Assurance Branch

Cc: James M. "Mike" Carlson, WDNR

## WPDES Permit and Nutrient Management Plan Inspection and File Audit U.S. ENVIRONMENTAL PROTECTION AGENCY, REGION 5

Purpose:	
Complaint Follow-up inspection	
Facility:	On the Art of the Marie of the Art of the Ar
Tag Lane Dairy	
Ex. 6. (Personal Privacy)	
Ixonia, Wisconsin 53036	
THE RESERVE THE PROPERTY OF THE PARTY OF THE	
NPDES Permit Number:	
WI-0063932-01-0	
The second of th	
Date of Inspection:	
April 27, 2017	
April 27, 2017	
EDA Danus antativas	
EPA Representatives:	312-886-1463
Cheryl Burdett	312-000-1403
CAFO Program Manager	
Burdett.cheryl@epa.gov	
0.1.37.11	212 252 0724
Carla Valdes	312-353-0724
Environmental Scientist	
Valdes.carla@epa.gov	
Facility Representatives: Ex. 6. (Personal Privacy)	Ex. 6. (Personal Privacy)
Ex. 6. (Personal Privacy)	
Ex. o. (i ersonai i iivacy)	The second secon
	7
Inspector Signature:	all!
Approval Date: 10/30   2017	Delication of the Authority of the St. Mar.
Approver Title: Ryan Bahr, Section 2 Chief,	Water Enforcement Compliance Assurance
<u>Branch</u>	
02 1	2
Approval Signature:	) elu-

On April 27, 2017, EPA followed up on a citizen complaint that alleged that Tag Lane Dairy Farm was discharging process wastewater from their abandoned vegetated treatment area (VTA) that discharges through a culvert under River Valley Road into an unnamed tributary that flows to the Rock River. The weather was overcast and raining.

EPA could not locate him, so they called their arrival.

EPA could not locate him, so they called their arrival.

EPA could not locate him, so they called their arrival.

EPA could not locate him, so they called their arrival.

EPA could not locate him, so they called their arrival.

EPA could not locate him, so they called their arrival.

EPA could not locate him, so they called their arrival.

EPA could not locate him, so they called their arrival.

EX. 6. (Personal Privacy) the office. EPA presented credentials and explained that there had been an anonymous complaint about alleged discharges from Tag Lane Dairy Farm's VTA.

EX. 6. (Personal Privacy) stated that he is collecting all the runoff from the feed pad area and checks the pump regularly to verify it is working and that no process wastewater has been flowing into the VTA.

EPA walked through the feed pad area and verified that all runoff from the feed pad area was being collected at the pump and that the pump was working and pumping all the process wastewater into Waste Storage Facility 1 (WSF 1). EPA checked other inlets from the production area to verify no other sources of process wastewater from the production area was entering the VTA. EPA did not observe any sources of process wastewater entering the VTA from the production area, at the time of the inspection.

However, EPA did observe some visible silage in the VTA, but because it has been wether that the solids were from prior flow that had entered into the VTA, but because it has been wether that has not been able to get into the VTA to clean out the solids. However, stated that no additional solids have been entering the VTA, since the interim measures were installed. EPA's documents received from Tag Lane Dairy Farm show that the interim measure were installed around October 18, 2016.

EPA's exit briefing with stated that at this time we did not observe any process wastewater from the production area discharging from the VTA to a water of the United States and that the pump in the feed pad area was working.

EPA asked if they could leave their yellow rubber boots on site and exited the facility.



Photograph: (P427001) Observing the collection pump.

Location: Northwest corner of feed storage area

Facing: Down

Date/Time: April 27, 2017 at 9:35 AM



Photograph:(P4270002) Looking down to verify water is below pump level.

Location: Northwest corner of feed storage area

Facing: Down

Date/Time: April 27, 2017 9:35 AM




Photograph: (P4270003) Collection pump - verifying level of water in collection pump.

Location: Northwest corner of feed storage area.

Facing: Down

Date/Time: April 27, 2017 at 9:35 AM



Photograph: (P4270004) Electrical box for pump that collects process wastewater off the feed storage area. Documents amount of flow, so Tag Lane Dairy Farm can record when the level is more than the pump can handle and results in an overflow.

Location: Northwest corner of feed storage area

Facing: East

Date/Time: April 27, 2017 at 9:35 AM



Photograph: (P4270005) Flows through the vegetated treatment area (red arrow illustrates flow direction).

Location: Northeast corner of the vegetated treatment area

Facing: southwest

Date/Time: April 27, 2017 at 9:39 AM



Photograph: (P4270006) Close up of the pathways within the vegetated treatment area (red arrow

illustrates flow direction).

Location: Northeast corner of the vegetated treatment area

Facing: southwest

Date/Time: April 27, 2017 at 9:39 AM



Photograph: (PA4270007) This trench was used to collect process wastewater from the feed pad prior to October 18, 2016. Since, the installation of the interim measures installed October 18, 2016, it is now collecting storm water that is being dispersed through the VTA.

Location: North of the VTA

Facing: west



Photograph: (PA4270008) Culvert that flows into collection area prior to going through the separation bar and into the vegetated treatment area. Originally designed to collect excess process wastewater from the silage feed pad area after a certain amount was collected and discharged into WSF 1, the remaining would gravity flow into the vegetated treatment area. The VTA has now been abandoned. At the time of the inspection, no flow was coming out of culvert.

Location: Southeast corner of vegetated treatment area

Facing: North

Date/Time: April 27, 2017 at 9:41 AM